

DISTINCTIVE LEARNERS EXCEPTIONAL LEADERS

FACILITY ASSESSMENT



PREAMBLE



Boyd ISD has a rich history of education that began in 1904 with the construction of the first school facility. The District is 213 square miles and serves residents in Boyd and a portion of the Briar community. Boyd ISD is strongly supported by residents and local businesses to provide excellent opportunities for advanced education which is vital to their success.

The safety and security of students, faculty and administrators is paramount at Boyd ISD and is reflected throughout this facility assessment report. Although some buildings are aging, the educational facilities of this district are well maintained and offer an excellent learning environment for advanced curriculum, fine arts and athletics. As reported by the Texas Education Agency (TEA), Boyd ISD is in compliance with required safety protocols but may be subject to change due to executive orders and recommendations from other agencies. This report will provide recommendations that may be considered necessary to improve Boyd ISD facilities and may reference these areas by descriptions and photographs.

Boyd ISD serves grades Pre-K through 12 and has a current enrollment of approximately 1,249 students and is a 3A school district as certified by UIL.


Boyd ISD educational facilities include the following:

- Boyd Elementary School
- Boyd Intermediate School
- Boyd Middle School
- Boyd High School



WELL MAINTAINED











CAMPUSES ASSESSED





- **Boyd Elementary**
- Boyd Intermediate/Middle
- Boyd High School
- **Athletics**



BOYD ELEMENTARY SCHOOL



Boyd Elementary School 500 East Morton Avenue Boyd, Texas 76023				
Year Built	1992			
Approx. Total Square Footage	53,898 SF			
Grades Served	Pre-K through 4			
Current Enrollment	472			

Building Levels







BOYD ELEMENTARY




General Assessment

Boyd Elementary School is a single story 53,898 sq ft facility constructed in 1992, and currently houses grades Pre-K through 4. The main entrance has a secure vestibule with a defined line of sight for the administration to receive students and visitors. The classrooms do meet current educational requirements and are generally, too small. The corridors are adequate for circulation but, the restrooms do not meet current TAS/ADA requirements. Corridors are VCT tile with 2 x 4 and 2 x 2 acoustical ceiling tiles. The entrance is well defined from the street level. There are 27 classrooms located inside a single building that are double-loaded corridors with three sets of restrooms including a library, book room, music room, cafeteria, gymnasium and administration offices for faculty. The parking surface and service roads are also in fair condition with adequate spaces for faculty and visitors. Accommodations for vehicular and bus traffic appear to be adequate and meet current safety requirements although pavement markings are fading and the parking light standards are not protected.











DOES NOT MEET TAS/ADA

DOES NOT MEET TAS/ADA

MEETS TAS/ADA







DOES NOT MEET TAS/ADA

DOES NOT MEET TAS/ADA

DOES NOT MEET TAS/ADA







DOES NOT MEET TAS/ADA









UNDERSIZED CLASSROOM

UNDERSIZED CLASSROOM

UNDERSIZED CLASSROOM









UNDERSIZED LIBRARY

DOES NOT MEET TAS/ADA

UNDERSIZED LIBRARY





AGING FINISHES AGING FINISHES EVIDENCE OF MOISTURE











SECURITY RISK SAFETY RISK SECURITY RISK





NEED HDPE DIVIDERS HDPE DIVIDERS PRESENT NEED HDPE DIVIDERS











INADEQUATE STORAGE

INADEQUATE STORAGE

INADEQUATE LIGHTING



NEEDS SECURE VESTIBULE

DETERIORATING WINDOW FRAME

DETERIORATING MORTAR









INADEQUARTE LIGHTING

DOES NOT MEET TAS/ADA

DOES NOT MEET TAS/ADA







INADEQUARTE DRAINAGE

INADEQUARTE DRAINAGE

INADEQUARTE DRAINAGE



SECURITY RISK SECURITY RISK SECURITY RISK









DETERIORATING PARKING/STRIPING

DETERIORATING PARKING/STRIPING

DETERIORATING PARKING/STRIPING

SUMMARY



General Condition Summary						
Interior Conditions Exteri		Exterior Cor	nditions	Site Conditions		
Flooring	Fair	Walls	Fair	Paving	Fair	
Ceiling	Good	Sealants	Fair	Striping	Poor	
Walls	Good	Window Systems	Poor	Sealants	Fair	
Doors	Good	Canopies	Fair	Sidewalks	Good	
Casework	Good	Roofing	Good	Landscape	Fair	
RR Partitions	Fair			Drainage	Poor	
Visual Display Boards	Good			Fencing	Poor	
ADA & Life Safety	Fair			Playground	Good	

RECOMMENDATIONS



- Determine the maximum student population for an elementary campus for current and future buildings
- As student population grows, expand current facility or consider building a second elementary school
- Relocate current library into renovated space to meet current TEA standards and expand classroom wing for education spaces that would be displaced
- Upgrade and replace kitchen equipment that is not working i.e. disposal
- Replace carpet throughout entire building
- Repair perimeter fence gates that are not aligned to improve security
- Install panic release hardware on exterior exit gates
- Repair roof leaks and address clogged condensate lines
- Replace any water damage ceiling tile due to storm water or leaks from a condensate line or plumbing
- Protect existing parking lot lights from damage by installing a concrete island with curbs

See Recommendations Tab for List of Standard District-Wide Recommendations



BOYD INTERMEDIATE/MIDDLE



Boyd Intermediate and Middle School 550 Knox Avenue Boyd, Texas 76023

Year Built	Intermediate School - 1980 Middle School - 1986		
Approx. Total Square Footage	70,735 SF Total		
Grades Served	5 through 8 398		
Current Enrollment			
Building Levels	1		







BOYD INTERMEDIATE/MIDDLE



General Assessment

Boyd Intermediate and Boyd Middle School are located on the same campus and share the library, cafeteria, gymnasium and a common connecting corridor. This facility previously served as the high school but has since been repurposed. The two schools are connected by a single corridor and both facilities have two central offices with separate entrances. The middle school appears to be aging more than the intermediate school. The finishes are continuing to wear and most restrooms do not meet current TAS/ADA requirements. Classrooms and the library are undersized and do not meet TEA standards.











NEEDS SECURE VESTIBULE

NEEDS SECURE VESTIBULE

NEEDS SECURE VESTIBULE











DOES NOT MEET TAS/ADA

DOES NOT MEET TAS/ADA

DOES NOT MEET TAS/ADA



DOES NOT MEET TAS/ADA

DOES NOT MEET TAS/ADA

DOES NOT MEET TAS/ADA









DOES NOT MEET TAS/ADA

DOES NOT MEET TAS/ADA

NEED SICK/INJURED SEPARATION










EVIDENCE OF MOISTURE DAMAGE

EVIDENCE OF MOISTURE DAMAGE

MISSING CEILING TILE












INADEQUATE STORAGE

INADEQUATE LIGHTING

GYM AGING RAPIDLY









NEED HDPE DIVIDERS

INADEQUATE ELECTRICAL

DETERIORATING FLOOR









INADEQUATE DRAINAGE

INADEQUATE DRAINAGE

INADEQUATE DRAINAGE







INADEQUATE HARDWARE

INADEQUATE HARDWARE

INADEQUATE ELECTRICAL







SAFETY RISK / GAS LINE NEEDS REPAINTED

SAFETY RISK / UTILITY LINES NEED REPAINTED

SAFETY RISK / UTILITY LINES NEED REPAINTED





MOLD / MILDEW PAVEMENT STRIPING FADING NEEDS RESTRIPING

RECOMMENDATIONS



- Recommend leadership consider various alternatives for this facility as the building is continuing to age and does not meet current TEA standards
- Set the standard for the capacity of future intermediate and middle schools
- Consider relocating the intermediate and middle school to another facility due to the age of the current building
- Consider moving the intermediate and middle school to the current high school campus and build a new high school campus
- Consider converting the existing intermediate and middle school to an early childhood facility
- Recommend classrooms be converted to alternative programs or storage
- Secure and isolate the locker rooms above the gymnasium that have potential asbestos
- Modify both entrances to create a secure vestibule and restrict public access to the shared library
- Reroute storm water from roof drains away from the building near the gymnasium
- Repair roof leaks and address clogged condensate lines
- Replace any water damage ceiling tiles due to stormwater or leaks from a condensate line or plumbing



BOYD HIGH SCHOOL



Boyd High School 700 Knox Avenue Boyd, Texas 76023		
Year Built	2010	
Approx. Total Square Footage	112,143 SF	
Grades Served	9 through 12	
Current Enrollment	379	
Building Levels	1	





BOYD HIGH SCHOOL



General Assessment

Although the high school is 23 years old, it appears to be relatively new and remains in good condition. The campus serves grades 9 through 12 with approximately 112,000 sq ft dedicated to education and customer service spaces. It has been well maintained and serves the Boyd ISD community as designed.











MEETS REQUIREMENTS

MEETS REQUIREMENTS

MEETS REQUIREMENTS











DOES NOT MEET TAS/ADA

MEETS TAS/ADA

NEED SICK/INJURED SEPARATION









INADEQUATE STORAGE

INADEQUATE STORAGE

INADEQUATE STORAGE








NEEDS SECURE VESTIBULE

INADEQUATE LIGHTING



EXTERIOR









ADA RAMPS NEEDS REPAINTING

ADA RAMPS NEEDS REPAINTING

DOES NOT MEET TAS/ADA

EXTERIOR





HANDRAIL MISSING / SAFETY RISK

INADEQUATE DRAINAGE

INADEQUATE DRAINAGE



RECOMMENDATIONS



- Review current property and consider building a new high school beginning with core facilities and designate areas for future classroom wings as the student population increases
- Consider the location of the future high school to be accessible to thoroughfares that will accommodate the traffic load
- Set the standard for the capacity of future high school and attendance zones
- Work closely with the City of Boyd to ensure the current and future transportation plan meet the goals of Boyd ISD
- Review the design of the current high school and consider converting to a middle school
- Install film over glass along corridors near the front entrance to increase security and reduce exposure
- Install commercial-grade splash guards near downspouts to reduce soil erosion
- Repair roof leaks and address clogged condensate lines
- Recommend wayfinding signage for the interior to identify sections of the building



BOYD ISD ATHLETICS







BOYD ISD ATHLETICS



General Assessment

The athletic facility buildings are a combination of brick veneer and sheet metal and are in good condition but have ADA-related issues that need to be corrected. The handicap ramps are fading, curbs are damaged and sealants are failing. The football field, track, and baseball field were recently upgraded with new artificial turf within the last year and all areas appear in good condition.



ATHLETICS





MEETS REQUIREMENTS

MEETS REQUIREMENTS

ATHLETICS






MEETS REQUIREMENTS

MEETS REQUIREMENTS

EXPAND WEIGHT ROOM



ATHLETICS







NEED HDPE PARTITIONS

NEED HDPE PARTITIONS

DOES NOT MEET TAS/ADA

RECOMMENDATIONS



- Locker rooms are undersized and do not meet current TEA requirements
- Restrooms need to be upgraded to meet current TAS/ADA requirements
- Toilets do not meet current TAS/ADA requirements
- Relocate the light switch inside one restroom located inside a toilet area and behind the partition wall.
- Expand the floor area of the weight room to accommodate the equipment and allow more space



DISTRICT-WIDE RECOMMENDATIONS



Security

- If the campus is greater the 20 years, consider either upgrading or replacing exterior doors with solid steel frames and mullions as a minimum to improve security
- Restore, refinish or replace damaged interior doors and install ADA compatible hardware
- Create a secure vestibule by replacing exterior doors that are considered aluminum store front type and add a second tier of doors
- Restore and refinish damaged interior doors and install ADA compatible hardware.
- Ensure peep holes are installed at any solid door that does not have a vision panel
- If possible, ensure line of sight is maintained in the secured vestibule
- Bullet resistant glass and film is recommended for all openings within secure vestibules
- Remove all wooden, plastic or rubber wedges, bricks and blocks used to prop doors open
- Remove all kick-down door stops from all doors
- Ensure each classroom has fire exit plan that is clearly visible and recommended to be enclosed in a frame with a glass cover
- Consider using a pad lock for all roof hatches



DISTRICT-WIDE RECOMMENDATIONS



ADA Compatibility

 Assess all openings to ensure each is compatible with requirements set by the Americans with Disabilities Act (ADA) and Texas Assessment Standards (TAS)

Risks

- Review and maintain the status of the AHERA report to determine if VCT and mastic is positive within any classroom, corridor, office or storage area. Typically, 9x9 floor tiles including some 12x12 floor tiles contain asbestos. The mastic or glue may also test positive and is often black. Also, some adhesives have test positive for dry erase boards.
- Seal all wall and ceiling penetrations including plumbing, structural members, electrical conduit and data lines with fireproof caulking as it penetrates the ceiling or wall.
- Number every exit/entrance door on both sides with an affixed decal and provide floor plan to local Police Department or Sheriff's Office
- Do not block access to any electrical panel



DISTRICT-WIDE RECOMMENDATIONS



Site

- Install a swale or French drain with grate to remove excess storm water near building and entrances as needed
- Install commercial grade concrete splash blocks below exterior downspouts to prevent soil erosion
- Repair or replace damaged downspouts
- Install concrete filled steel bollards near downspouts exposed to heavy vehicular traffic especially in service and delivery areas

Building

- Use protective wire mesh above CMU walls inside gymnasiums to prevent trapped basketballs, volleyballs etc.
- Install room signage with assigned number for every room at proper height
- Remove all content from electrical rooms and post a sign that prohibits the storage of any item
- Verify every room has a return air duct and supply air duct to maintain air quality
- Do not use metal toilet partitions in any restroom
- Replace all metal toilet partitions with HDPE partitions
-



ANNUAL INSPECTIONS LIST



Annual Inspections List		
Roofs	Septic Systems (if applicable)	
Gutters	Water Wells (if applicable)	
Irrigation	Fire Suppression Water Storage	
Landscape	Fire Suppression	
Drainage Culverts/Catch Basins	Intercom System	
Pavement Striping	Access Control/Locking Mechanisms	
Parking and Road Signs	Lighting	
Water Heaters	Door Hardware	
HVAC	Weight-room Equipment	
Toilet Partitions	Wall Pads, Goals, and Volleyball Net	
Plumbing Fixtures	Lockers	

ANNUAL INSPECTIONS LIST



Annual Inspections List		
Replacement	Interval	Cost/Unit
Concrete Pavement/Parking	20 Years	\$15.00/SF
Asphalt Pavement/Parking	10 Years	\$12.00/SF
Pavement Striping	3 Years	\$0.25/LF
Re-stripe Parking Lots	3 Years	\$0.25/LF
Re-stripe Fire Lanes	3 Years	\$0.50/LF
Re-caulk Parking Lots	6 Years	\$2.00/LF
Re-seal Expansion Joints	10 Years	\$2.00/SF
Re-seal Joints Between Sidewalk and Buildings	5 Years	\$3.00/LF
Masonry Paint	8 Years	\$6.00/SF
Clean and Seal Masonry	10 Years	\$7.00/SF
Re-coat Plaster Fascia and Soffits at Entry	8 Years	\$12.00/SF
Chain-link Fencing	20 Years	\$12.00/SF

TAKEAWAYS



Elementary Campus

- Will be at capacity next year
- District should begin planning to determine ideal BISD campus size(s)
- Explore options to accommodate growth
 - Addition?
 - New campus?

Intermediate / Middle School Campus

- Entire campus aging quickly
 - Middle School/Junior High in immediate need of long-term plan
- Master-plan for eventual replacement of this campus
 - Phased replacement of entire campus?
 - Move to High School?

High School Campus

- Designed as middle school?
- Replace High School and move Middle School to current HS campus?

